



**DIPACO**  
**DIESEL**  
**PARTS**  

---

**U S A**

## PRODUCT INFORMATION

**FI-45**

May 1994

File: Cummins Fuel

### AFC Tach Drive Plug. Gear Pump Inlet Elbow and Adapter Front Cover Seal Repair Kit

---

#### AFC Tach Drive Plug

For fuel pumps using or being converted to an electronic tach, we have added the AFC tach drive plug, part number **D3040815**.

#### Gear Pump Inlet Elbow and Adapter.

In the last Update we introduced the **DPE10500** gear pump elbow. Responding to your requests, the two components of the **DPE10500** are now available individually. **DPE10501** is a longer version of the standard inlet elbow with pipe threads. This elbow can also be used in place of the Komatsu/Cummins elbow **D6610-71-2571**. **DPE10502** is an adapter which screws onto the **DPE10501** elbow and changes the pipe threads into straight threads for newer style gear pumps.

#### Front Cover Seal Repair Gasket Set.

Fuel shops often do just a minor overhaul on a Cummins fuel pump to repair front seal leaking. We now have a special front cover seal repair kit, part number **DPE890015**. The kit includes the following parts:

1	<b>D100764</b>	Gasket
1	<b>D3063052</b>	Gasket
2	<b>D3062676</b>	Seal
1	<b>D212603</b>	Seal
1	<b>D212607</b>	Tach Shaft
1	<b>D3018682</b>	Capscrew
1	<b>D3000446</b>	Cover
1	<b>D3048341</b>	Gasket
1	<b>D163945</b>	Snap Ring
2	<b>DS2286</b>	Screw
1	<b>D162426</b>	Spider
1	<b>D100478</b>	O-ring
1	<b>DPE30200</b>	Decal
1	<b>D212601</b>	Main Shaft

---

**ADMINISTRATION**  
(775) 329-7511  
(775) 329-9740 Fax  
admin@dipaco.com E-mail

**DIPACO, Inc.**  
105 East Parr Blvd.  
Reno, Nevada, 89512 • USA  
Internet: www.dipaco.com

**SALES**  
Toll Free (800) 648-4720  
Toll Free Fax (888) 320-7761  
E-mail sales@dipaco.com