


**Repair Parts for PLD Style Pumps**

**DIPACO** has available a wide range of repair parts for Bosch PLD100 (Freightliner, Mercedes Atego and MBE900), PLD110 (Freightliner, Mercedes Actros and MBE4000), and PLD100-110 Type B (Mack, Renault, DAF, KHD) style pumps.

The following items are common to all three style of pumps. **RTF26022** is the repair kit for PLD pump solenoids. The repair kit includes four solenoid screws plus the internal solenoid seal rings. **RTF26024** is the solenoid armature screw.

**RTF26021** is the anti-tamper torx bit used to remove original solenoid screws. **DPE99051-T156** is the torx bit used to install and remove **DIPACO** solenoid screws. The **DPE99051-T156** is also included in the **DPE99051** torx bit kit.

**RTF26035** is the external o-ring kit for the PLD100-110 Type B pump used in Mack. **RTF25084** is the external o-ring kit for the PLD100 while **RTF26085** is the external o-ring kit for the PLD110 pump.



RTF26022  
Solenoid Repair Kit



RTF26021  
T20 5 Point Solenoid Screw Torx Bit  
DPE99051-T156  
T15 6 Point Solenoid Screw Torx Bit



RTF26024  
Solenoid Armature Screw



RTF25084  
External O-Ring Kit  
PLD100



RTF26035  
External O-Ring Kit  
PLD100-110 "B"



RTF26085  
External O-Ring Kit  
PLD110