

**Service Kit For GM 6.6L
Duramax LB7 Common
Rail Injectors**

DIPACO
DIESEL
PARTS
U S A

DIPACO now offers an injector service kit for repairing 2001 – 2004 GM 6.6L Duramax LB7 common rail injectors. Part number for the kit is RTF25169.

The kit includes commonly used internal and external parts for repairing 8 injectors. We also offer an injector service kit with enough parts to repair 100 injectors. Part number for that kit is RTF25169-100.

Complete contents of the service kits can be found below.

RTF25169		
Part Number	Description	Qty
RTF25083	Injector Check Ball	8
RTF25106	O-Ring, Stator	16
RTF25140	Seal Ring, Control Valve	8
RTFF00VC17105	Washer Control Valve	8
D94011699	O-Ring, Body (External)	8
D94011701	O-Ring, Inlet Fitting	8
D97216082	Nozzle Washer	8

An Employee Owned Company

12693 Old Virginia Road
Reno, NV 89521
800.648.4720

DIPACODTECH.com