

Automatic Timing Advance Repair Kit for Caterpillar 3406B/C Pumps

DIPACO has available a kit for repairing the automatic timing advance in Caterpillar 3406B/C fuel pumps, part number DPE3410. The kit includes the weight carrier, weights, dowel pins, and the spool bearing race. Below are the DPE3410 kit contents:

Part Number:	Description:	Quantity:
D1W5434	Weight Carrier	1 each
D1S5440	Weight Dowel	4 each
D7N7264	Weight	4 each
D4N2927	Bearing Race	1 each