


Seeding Problems?

Hydraulic Oil runs too hot?

Heavy dew in the morning delays seeding?



Solution:

AIRGUARD BLOCKAGE PREVENTION SYSTEM

Reduces oil temperature by
20°C / 68°F

Heats air inside the drill by
10°C / 50°F

Drops Relative Humidity by
50%

CALL 1.306.914.3553 or 1.604.744.0070 for more information
www.airguardproducts.com



With AirGuard Blockage Prevention System



Without AirGuard Blockage Prevention System


AIRGUARD
SEEDING PRECISION