


**Repair Kit For CP1-K
Sprinter Van High-
Pressure Pump**

DIPACO
DIESEL
PARTS
U S A

DIPACO introduces a repair kit, part number RTF25188, for the CP1-K high-pressure pump used on the 2000 - 2003 Sprinter Van with the OM612 engine. The repair kit includes all of the oil seals, o-rings, seal rings and washers needed to rebuild the high-pressure pump.

Due to a design change to the element cover seal ring there are early and late style CP1-K high-pressure pumps in service. The RTF25188 kit includes both style seal rings so only one kit is required to service both pumps.



RTF25188

An Employee Owned Company

12693 Old Virginia Road
Reno, NV 89521
800.648.4720

DIPACODTECH.com