

**Nozzle Pressure Spring  
For Detroit Series 50 +  
60 Injectors**

**DIPACO**  
**DIESEL**  
**PARTS**  
**U S A**

DIPACO now has the nozzle pressure spring, part number RTF26232, for the Series 50 and Series 60 injectors.

In-service failures of the nozzle pressure spring are common. It is recommended that a new nozzle pressure spring be installed whenever a Series 50 or Series 60 injector is repaired. Recommended valve opening pressure is 4800 – 5200 PSI.



**RTF26232**

*An Employee Owned Company*

12693 Old Virginia Road  
Reno, NV 89521  
800.648.4720

**DIPACODTECH.com**